













## **CURRENT WORK**

- Structural steel is being erected
- Trusses and roof joists are being installed
- Metal panel installation at the main entrance continues
- Preparation for the north access gate and concrete driveway is beginning



During design, the trusses running north and south were revised to be significantly larger so they could span the entire floor & avoid using interior columns.

## JOBSITE RECAP









- 1) The 20' exterior overhead door leading to the main exhibit hall has been installed
- **2)** Diffusers for the lobby HVAC system have been installed and painted
- **3)** Conduit and wire for the building's electrical system have been installed and we are ready for permanent power
- **4)** The equipment pads and sidewalks at the rear of the building have been poured. The equipment is ready to be placed upon delivery.



